

SECRET

Declassification Review by NGA/DoD

OUT54867

S E C R E T 132132Z

1965 JAN 18 22 05Z

25X1

1. CAMERA B 15 WAS USED IN MISSION 3984 FLOWN ON 15 JANUARY 1965. PROCESSING WAS ACCOMPLISHED BY NAV RECON TECH SUPPCEN.

2. ORIGINAL NEGATIVE:

A. THE EXPOSURE WAS ADEQUATE AND THE RESOLUTION IS GOOD.

B. 9R SIDE: SPOT STATIC DISCHARGES, EDGE FOG, AND OCCASIONAL ROLLER CHATTER MARKS ARE PRESENT NEAR THE OUTBOARD EDGE ALONG WITH CONTINUOUS ROLLER CHATTER AT THE INBOARD EDGE THROUGHOUT THE MISSION.

19 JAN 1965

A PLUS DENSITY STREAK 3.3" FROM THE INBOARD EDGE IS PRESENT THROUGHOUT. ANOTHER PLUS DENSITY STREAK APPEARS 4.4" FROM THE EDGE AND CONTINUES INTERMITTENTLY TO THE END OF THE MISSION. SEVERAL INTERMITTENT PARALLEL SCRATCHES SPACED APPROXIMATELY 0.25" APART ARE LOCATED WITHIN THE 1.5" ADJACENT TO THE INBOARD EDGE FROM FRAME 0001 TO 1064. THE MOST PROMINENT OF THESE SCRATCHES IS 1.0" FROM THE EDGE. ABRASIONS, SCRATCHES, AND CREASES EXIST IN FRAMES 1332 AND 1333. THESE WERE CAUSED BY THE TITLER. A WAVY PLUS DENSITY STREAK IS PRESENT WITHIN THE 1.0" NEAREST THE OUTBOARD EDGE IN FRAME 1424 TO 1451. A HEAT SPLICE OCCURS IN FRAME 1060 AND A MANUFACTURING SPLICE WITH ASSOCIATED LIGHT LEAKS IS PRESENT IN FRAME 1195.

| COPIES RECEIVED | | | |
|-----------------|-------------|------|-------|
| CyNo. | Office | Act. | Rec'd |
| SAME | Master File | | |
| 2 | OS | | |
| | ADMIN | | |
| | SEC BR | | |
| | P&DS | | |
| | CSD | | |
| | IPD | | |
| | PD | | |
| 4 | PSD | | |
| | STID | | |
| | PAG | | |
| | CIA/PID | | |
| | DIAXX-4 | | |
| | SPAD | | |
| | NSA LO | | |
| | DIAAP | | |
| | | | |
| | | | |
| | | | |
| | Des. yed | | |

C. 9L SIDE: EDGE FOG AND ROLLER CHATTER ARE PRESENT ALONG THE INBOARD EDGE OF THE FIRST 75 PERCENT OF THE MISSION. OUTBOARD EDGE FOG IS CONTINUOUS THROUGHOUT THE MISSION. DUE TO PROBLEMS ENCOUNTERED DURING PROCESSING THE FILM WAS TORN AT FRAME 64. AN

SECRET

GROUP 1
Excluded from automatic
downgrading and
declassification

25X1

-2-

EMERGENCY CUT WAS MADE AND THE TEAR WAS REPAIRED WITH TAPE. BEGINNING AT THE SPLICE ON FRAME 64 THERE IS A PLUS DENSITY STREAK 0.25" FROM AND PARALLEL TO THE INBOARD EDGE. THE STREAK ENDS AT A HEAT SPLICE ON FRAME 1316. THERE ARE OTHER RANDOM LONGITUDINAL PLUS DENSITY STREAKS INTERMITTENTLY THROUGHOUT THE MISSION. ON FRAMES 831 TO 840 THERE ARE SEVERAL EMULSION LIFTS. AT THE DATA CHAMBER END OF EACH FRAME APPROXIMATELY HALF WAY BETWEEN THE FILM EDGES THERE IS A MINUS DENSITY STREAK WHICH APPEARS TO BE AN OBSTRUCTION CAUSED BY FOREIGN MATTER ADHERING TO THE FORMAT FRAME.

D. BOTH SIDES: THE LAST TITLED FRAME ON EACH SIDE IS 2181.

E. THERE WERE NO APPARENT CAMERA MALFUNCTIONS.

3. POSITIVE:

A. PRINTING AND PROCESSING WERE GOOD.

B. PI SUITABILITY IS GOOD.

C. CLOUDS COVER LESS THAN 1 PERCENT OF THIS MISSION.

S E C R E T

--END OF MESSAGE--

1